DELHI JAL BOARD

(GOVT. OF N.C.T. DELHI)

ZONAL LABORATORY WATER HAIDER PUR



TEST REPORT

Water Sample Vide Challan No.25 dated 07.06.2022 collected from drinking point of school (DJB tanker Supply) HARI VIDYA BHAWAN SENIOR SECONDARY SCHOOL, K-II/600, SANGAM VIHAR, New Delhi-110080

	DADAMETEDE	UNITS	S195
S.N	PARAMETERS		07/06/2022
1.	Date of collection/Receipt		09/06/2022
2.	Date of Analysis	Hazen	Clear
1.	Colour	Hazen	No. Objection
2.	Odour		1.4
3.	Turbidity	N.T.U	
4.	P ^H value		7.7
5.	Electrical Conductivity	umos/cm	245
6.	Total dissolved Solids	(mg/1)	-
	CHEMCIAL EXAMINATION		
1.	Phenolphthalein Alkalinity	(mg/1)	Nil
2.	Total alkalinity	(mg/1)	83
3.	Total hardness	(mg/1)	120
4.	Carbonate hardness	(mg/1)	86
5.	Non-carbonate hardness	(mg/1)	43
6.	Calcium as Ca	(mg/1)	35
7.	Magnesium as mg	(mg/1)	10.6
8.	Ammonia (free& saline)	(mg/1)	Nil
9.	Nitrite-nitrogen(N)	(mg/1)	Nil
10.		(mg/1)	-
11.		(mg/1)	34
12		(mg/1)	13
13.		(mg/1)	Tr.
14.	Iron (Dissolved)(Fe)	(mg/1)	0.07
15.		(mg/1)	0.30
16.	Cyandies(CN)	(mg/1)	Abst.
17.	Residual Chlorine	(mg/1)	1.0
	BACTERIOLOGICAL EXAMINATION		
1	Coliform per 100 ml at 37°c	MPN/100	0

REMARK:

The Sample S195 Confirm to IS: 10500-1993. Hence, it is fit for drinking purpose

Chemist/Bactgeriologist

Hari Vidya Bhawan K-II/600, Sangam Vihar New Delhi-110080

Hari Vidya Bhawan K-II/600, Sangam Vihar New Delhi-110080



MUNICIPAL CORPORATION OF DELHI PUBLIC HEALTH DEPARTMENT: SOUTH ZONE **GREEN PARK, AUROBINDO MARG NEW DELHI 110016**

No: DHO/SZ/2023/ D 555

Dated31 ... 5.2 1

SCHOOL HEALTH CERTIFICATE

1. Name of the School

Hari Vidya Bhawan Situated

2. Address

K-II/600, Sangam Vihar, New Delhi-110080.

3. No. of Shift

Morning

Timing 8AM to 2PM

4. No. of Students: Boys

1063

515 Total 1578

5. No. of Staffs: Male

31 Female

75 Total 106

Details of Accommodations present in School

1. Floor Space in the Classroom Sufficient/insufficient : Sufficient

2. The Classrooms are Well Lighted/ill lighted: Well Lighted

3. The Classrooms are Well Ventilated/ill ventilated: Well Ventilated

4. The Classrooms are kept / Not kept Neat & Clean: kept Neat & Clean

5. The Classrooms/Building requires/ do not required Whitewash etc. Whitewash

6. The Drinking Water is Wholesome/ not wholesome: Drinking Water is Wholesome

7. The Latrine arrangement is Sanitary/insanitary: Sanitary

No. of toilets seats for student

- 1. One latrine-cum-urinal is required for 25 female students are sufficient.
- 2. One latrine for 40 male students is required is sufficient.

3. Separate Toilet arrangement for staff present: Yes/No

: Yes

4. The Overall facilities: Good/ Adequate/Inadequate

: Good

If Building Department or any other Govt. agency takes actions against u/a constructions or any dispute, then the Health Certificate will be stand cancelled/revoked without any further intimation in this regard.

(-II/600, Sangam Vihar

K-II/600, Sangam Vihar New Delhi-110080

Deputy Health Officer South Zone, SDMCtal Ly. Health Officer/SZ